

## **Tools & Accessories**

Only clean products, tools, clothing and footwear should be used when working with ***hertalan.***

The following tools are recommended for use when installing ***hertalan:***

- Scissors (large & small)
- Compression Rollers: silicone 40mm, 28mm and 5mm Brass.
- Leister Triac hot air gun with 40mm and 10mm wide drilled nozzles.
- Tape measure or folding rule
- Silver Pens
- Chalk Line
- Hollow Punches
- Mastic Guns.

## **Chapter 3**

## **General Guidelines**

When installing roofs using **hertalan** products, it is important to fit the membrane in full accordance with this manual and any subsequent instructions issued by **hertalan**, use of the correct accessories will ensure the high quality of the finished project.

The following is a list of general principles to be adopted when installing **hertalan**:

- **hertalan** is an elastic material and must never be fitted in tension.
- Tension can be induced in **hertalan** by our manufacturing process, and the rolling and folding of the material. This tension must be released prior to the installation of the **hertalan** membrane. This can be achieved by unfolding the material on the roof and allowing it to "relax", this is achieved by laying the membrane flat for at least 45 minutes prior to installation.
- **hertalan** easy.cover prefabricated membranes offer made to measure roofing with rapid installation.
- When ordering, allowances should be made to include for laps, upstands, parapets etc. and to ensure that all details are included for within the dimensions.
- Only adhesives and sealants recommended by **hertalan** are permitted. **hertalan** is a complete waterproofing system and every component is designed to compliment each other and create the full system. Use of material other than those recommended will adversely effect the performance of the installation and **hertalan** (UK) Ltd will not accept any responsibility should failure occur. It is not permitted to dilute the materials nor should they be used in temperatures below 5°C. The use of bituminous products as an adhesive is not permitted.
- All surfaces to be adhered to must be clean, dry and free from oil and grease. The substrate to receive the **hertalan** must comply with conditions described in chapter 4 and all works to the substrate should be completed prior to application of **hertalan**.